IN THE SPECIFICATION

Please amend the specification as follows:

Please replace page 8, lines 13-23 through page 9, lines 1-2 with the following:

In a similar manner, two-dimensional physical controls provide data for two variables. Figure 2 is an illustration showing a plurality of exemplary two-dimensional physical controls that can be present in a system. As will be described in greater detail subsequently, two-dimensional physical controls are physical controls that provide data for two variables. As shown in Figure 2, two-dimensional physical controls can include, for example, a mouse 200, a trackball 202, a touch screen 204, or any other physical control that provides data for essentially two variables. As above, it should be noted that two-dimensional controls are not limited to those illustrated in Figure 2 and can include any type of device capable of providing data for two variables. Of course, more than 2D controls are envisioned. For instance, control may ~~includetracking~~ include tracking x, y, and z coordinates by having a user wear gloves that include sensors, and the sensors are detected to identify the glove location to provide 3D control. In addition, however, dimensions beyond 3D may be possible with appropriate processing.